

LOOKING EAST.

GABLE CORNING NOT SHOWN
ON DRAWING BY TYRER 1867.

THE ANGLE BLITRESSES
OF THE NAIVE DO NOT
APPEAR ON THE DRAWING
BY TYRER DATED 1867.

NORTH SIDE OF
CHURCH REMAINS
LARGELY AS BUILT
IN NORMAN PERIOD.
THERE ARE SOME
SMALL AREAS OF
REFACING.

ORD. B.M. 71.341

CONCRETE TILES TO ROOF
ARE A RECENT REPLACEMENT.

LINE OF W. FRONT
PRIOR TO DEMOLITION
EARLY IN 19. C.

STONEMWORK TO S. WALL OF NAIVE
ABOVE 1 M LEVEL APPEARS TO BE
A 19 CENT REFACING.

PATH LEVEL

EXISTING FOUNDATIONS
AS EXPOSED DURING ARCH.
EXCAVATIONS 1979/80

PATH

W. FRONT RESULT IN
PRESENT POSITION
C. 1800.
L.C. WINDOW
REINSTATED.

WEST ELEVATION.

